

Digitech® **Pro** Solutions

Working with Digitech **Pro** Solutions means working with less limits!

Remote Enter Button

When working with the Digitech® Professional or DP II in confined spaces, in log jams and piles of logs, the Remote Enter Button will simplify execution and registering of measuring results. The button is placed on the moveable handle side of the caliper. You can choose to register your measuring results with the Digitech terminal enter button or the Remote Enter Button. Scaling and calibration will be less tiresome and easier to execute. The button is also great for large scale inventory work. The Remote Enter Button is factory assembled and compatible with all Haglöf Sweden software including the Skalman® v6.



Art.no	Description	Art.no	Description
13-240-1201	Digitech Professional 500 with Remote button	13-400-1201	DP II 500 mm with Remote Button
13-240-1202	Digitech Professional 650 with Remote button	13-400-1202	DP II 650 mm with Remote Button
13-240-1203	Digitech Professional 800 with Remote button	13-400-1203	DP II 800 mm with Remote Button
13-240-1211	Digitech Professional 18" with Remote button	13-400-1211	DP II 18" with Remote Button
13-240-1212	Digitech Professional 24" with Remote button	13-400-1212	DP II 24" mm with Remote Button
13-240-1213	Digitech Professional 30" with Remote button	13-400-1213	DP II 30" mm with Remote Button

- Log measuring
- Cross scaling
- Measuring in piles
- Standing tree inventory
- Large tree diameters

NEW!

DP DME for your Computer Caliper!

NEW DME adapter for the Digitech Professional and DP II - Haglöf Swedens® **proven and tested ultra sound technology that really works for distance measuring in the forest!**

The DP DME distance measurer is a much requested accessory for the Digitech Professional and the DP II. The DP DME offers accurate and quick measuring results in a simpler ways and answer to the eternal question: - **Is the tree within or outside of the sample plot limits?** The DP DME delivers the measuring results from the center of the sample plot. Paired with data from the computer caliper on the tree diameter, the automatic answer comes up on the tree's position as in, or outside, the plot. The DP DME measures distances with **our classical ultrasound technology**, tested and proven functional and reliable in instruments such as the Vertex IV and the DME. Battery and display are supplied from the computer caliper, and all instrument functions are software run. The DP DME will work with most Haglöf Sweden software applications after upgrading!



The DP DME operates with the DP II or Digitech Professional and the transponder T3. Tested reliable field ready technology!

DP DME

Protocol:	NMEA
Interface:	RS232 19200,8,N,1
Accuracy:	1% or better when calibrated
Unit:	cm (transform to other units is made in receiving software program)
Battery:	3V external feed
Effect:	25mW
Distance:	30m or better
Dimensions:	LxBxH 53x31x31mm, 2"x1.2"x1.2"
Weight:	20g, 0.7oz
Accessories:	Transponder T3, Plot staff

Art no	Description
13-600-1064	DP DME, 360 adapter, transponder T3 & monopod. Software for computer caliper not included!
13-600-1065	DP DME Measuring unit only
15-104-1004	T3 Transponder
15-104-1005	Monopod/Plot Center Staff
15-104-1001	Adapter 360 degrees